








OLAF BIURKO




#	ART. NR	QUANTITY
1	401	1
2	402	1
3	101	1
4	102	1
5	103	1
6	510	1
7	801	1
8	001	1
9	701	3
10	301	6
11	305	3
12	050	3
13	850	1




 A	 D1	 C	 E	 P1	 F1
45	26	26	26	40	6
3.5x13mm	L=350				
 P2	 PR	 F10	 I4		
4	1KPL	40	3KPL		

 R3	 S1
3	3







1

	$\varnothing 15/12\text{mm}$ 	$\varnothing 8 \times 30\text{mm}$ 
D1	C	A
6	8	12







2

	$\varnothing 8 \times 30\text{mm}$ 	$\varnothing 4.0 \times 16\text{mm}$ 
D1	A	P1
8	9	18
$\varnothing 15/12\text{mm}$ 	$3.5 \times 13\text{mm}$ 	
C	P2	I4
6	4	3KPL
$L=350$ 		
PR	F1	
1KPL	6	

DO KROKU
TO STEP

9






3



E

4






4



E

2






5



E

2






6




E


6





3x



	
F10	C
15	6




3x








M4.0x23mm  R3 3	 S1 3
---	--



3x



10



11



12

