

Assembly Instructions / Navodila za montažo/Montageanleitungen

ZOJA



NO	PARTS	QTY
A (base)		X 1
B (nail)		X 5
C (foot rest)		X 1
D (gas lift)		X 1
E (spanner)		X 1
F (plate)		X 1
G (screw) (6*16mm)		X 4
H (seat)		X 1
I (back rest)		X 1
J (screw) (6*30mm)		X 8

