






Assembly Instructions / Navodila za montažo/Montageanleitungen PENOA

NO PARTS QTY


* Notice: Just fix the screws but do not tighten them at the beginning, adjust and tighten them after step 3.

A (spanner)		X 1
B (screw)	 (M8*14mm)	X 2
C (leg)	 (Screw holes with thread)	X 1
D (leg)	 (Screw holes without thread)	X 1
E (screw)	 (C6*30mm)	X 4
F (foot rest)		X 2
G (seat)		X 1
H (screw)	 (M6*25mm)	X 4


1  Connect the 2 legs by screwing from the holes of leg D (without screw thread) to leg C (with screw thread).



2



3



4

